

Massachusetts State Police provide another installment in their truck team's "What Could Go Wrong?" series

"We are happy to provide another installment in our Truck Team's "What Could Go Wrong?" series.

A Trooper from the MSP's Commercial Vehicle Enforcement Section came across this sight on the Southeast Expressway at Granite Avenue one day last week.

The truck (and the truck it was carrying) were headed to Chelsea and from there were going to be loaded onto a boat for transportation out of the country.

In addition to the obvious unsecured load and overweight violations, the Trooper also found the truck on the road had faulty brakes and the operator was illegally using a repair plate."-Massachusetts State Police.



Massachusetts State Police photo.



Massachusetts State Police photo.